Conditions for admittance to ON Semiconductor

- 1. Entry and moving on all ON Semiconductor premises is permitted only in the accompaniment of an ON Semiconductor representative.
- 2. Instructions of an ON Semiconductor representative have to be followed.
- 3. Places where personal protection devices have to be used are indicated by pictographs.
- 4. All safety labeling, symbols, signs, and signals have to be followed.
- 5. The badge must be worn visibly all the time. Ways how to wear the badge are pictured at each gatehouse of the ON Semiconductor buildings.
- 6. Visitors are obligated to inform an ON Semiconductor representative about an injury or urgent health problem.
- 7. It is prohibited to approach any equipment, machines, devices, and stored material without authorization of an ON Semiconductor representative.

EVACUATION PROCEDURE

Evacuation is triggered by continuous signal sirens.



Use marked emergency exits (leading to meeting points) for evacuation. There are floor plans with emergency exits in each workplace.

The nearest emergency exit has to be used for evacuation. In case of fire or other danger in the respective emergency exit, an alternate emergency exit has to be used. In case of evacuation, please report to the designated meeting point.

Using lifts during evacuation is prohibited.



ON Semiconductor is certified according to ISO 14001 and OHSAS 18001.

Version 10/18/2018

Important entrance information



The Czech traffic law is applicable on all ON Semiconductor premises. There is a maximum speed of 25 kph in parking lots.



Each driver must always take extra care and caution towards other road users.



Smoking is prohibited on all ON Semiconductor premises.



No photographing and recording is allowed.



Parking is allowed only in designated areas.



Entrance prohibited.

Prohibited items:













IMPORTANT PHONE NUMBERS











